IN UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 6,991,960

Docket No: 2269-4348US

Issue Date: January 31, 2006

Patentee: James J. Howarth

P File: METHOD OF SEMICONDUCTOR DEVICE PACKAGE ALIGNMENT AND

METHOD OF TESTING

DEC 2 7 2007

REQUEST FOR CERTIFICATION OF CORRECTION

MADEMIC Ommissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

ATTN: Certificate of Correction Branch

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. Two copies of the text of the Certificate in the suggested form are enclosed.

Pursuant to 1.20(a), the examiner is authorized to charge the Certificate of Correction fee of \$100.00 to the Deposit Account No. 13-3092.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

12,	/28/2007	ZJUHAR1	00000024	133092	6991960
01	FC:1811	1	00.00 DA		

Respectfully submitted,

DEC 3 1 2007

Certificate

Customer Number: 26809

of Correction

Date: December 20, 2007

Russ Sliter

Reg. No. 39,838

CERTIFICATE UNDER 37 CFR § 1.8: The undersigned hereby certifies that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450 Alexandria, VA 22313-1450, on this 20th day of December 2007

Kyrstin Ryan	Rysli Lyll		
Name	Signature		

12 +1 P



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Name	Signature			
Kyrstin Ryan	Kysti Ger			
CERTIFICATE UNDER 37 CFR 1.8: The undersigned Service with sufficient postage as first class mail, in an e Alexandria VA 22313-1450, on this 20th day of December 13.	hereby certifies that this correspondence is being deposited with the United States Postal envelope addressed to: Commissioner of Patents and Trademarks, P.O. Box 1450, per 2007.			
	Russ Sliter Reg. No. 39,838			
Date: December 20, 2007 By:	Lunch Stiffer			
Resp	pectfully submitted,			
Customer Number: 26809				
·	dit overpayment to Deposit Account No. 13-3092.			
-	N4			
Authorization to charge the Certificate of Correction fee of \$100.00 to the Deposit Account No. 13-3092 Request for Certificate of Correction. Certificate of Correction Form - PTO-1050 (in duplicate) A return postcard.				
We are transmitting herewith the attached:				
Commissioner for Patents Office of Patent Publication ATTN: Certificate of Correction Branch				
TESTING				
	DEVICE PACKAGE ALIGNMENT AND METHOD OF			
Issue Date: January 31, 2006	Docket No: 2269-4348US			
Patent No.: 6,991,960	Group Art Unit: 2815			
Applicant: James J. Howarth	Examiner: Jose R Diaz			
THOSE STATE OF THE				

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

- 4, . h

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO

: 6,991,960

Page (1) of 1

DATED

: January 31, 2006

INVENTOR(S)

: Howarth

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (56), under "U.S. Patent Documents", in column 1, line 3, delete "Brunner" and insert - - Bruner - -, therefor.

In column 8, line 41, in Claim 1, before "surface" insert - - forming at least two channels through the semiconductor device package from a first major - -.

In column 9, line 22, in Claim 7, after "holes" delete "the".

In column 10, line 5, in Claim 13, after "holes" delete "the".